	i																																					
	ż	HMIS	Label	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
	M SAIPA		Gauge	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	poog	poog	Good	Good									
JACK	t SYSTE	Nozzle/	Hose	Good	Good	Good	Good	Good	Good	Good	Good	poog	Good	Good	Good	Good	Good	Good	poog		Bood	Good	Good	Good	Good	Good	Good	Good	Good									
OR:	SAFETY 1st SYSTEM SAIPAN	Damage/	Corrosion	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
INSPECTOR			Weight	Good	Good	poog	poog	Good		Good	Good	Good		Good	Good	Good	Good	Good		Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	,								
		Tamper	Seal	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
12/. 7		Operating	Instr.Label	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good		Good	Good	Good	Good									
DATE:	TION OF FIRE EXTINGUISHE.	Access/	Visibility	Good	Good	Good	Good	Good	Good	Good		Good				Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good										
	ON OF FIF	Proper	location	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good		рооб	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
nar-ska	MONTHLY INSPECTION		Location	Reception	CONTROL		LOBBY HALL WAY	ADMIN HALL WAY	STAFF ENTRY	STAFF LOUNGE	KITCHEN	LIBRARY	CLASSROOM A	CLASSROOM B	WEIGHT ROOM	VOCATIONAL	INTAKE	UNIT A DRYROOM	UNIT A POD A	UNIT A POD B	OOM	UNIT B POD A	UNIT B POD A	,	ROOM			UNIT A AIRCON RM.										·
TOMER:		SERIAL	NUMBER#							SP784078	SN821604	SP784079	SP784062	SP784089	SP784064	MV080697	MV080677	MV080697	MV080684	MV080685	RB661426	19 MV080720	20 MV080724	SN821605	SN821601	SP784065	SN821602	SN821600	SN821603									
<u>.</u>	1				2	က			9	7	∞	6	10	7		13	14	15		17	78	19	20			23	24	25		27	28	29	30	31	32	33	34	35

DYS-JDU			DATE:	11 /07		INSPECTOR	TOR:	JACK		
MONTHLY INSPECTIO	~	N OF FI	TION OF FIRE EXTINGUIS.	3UISi .₹			SAFETY 1st SYSTEM SAIPAN	st SYSTE	M SAIPA	Ä.
<sup>1</sup> d]	Jd,	Proper	Access/	Operating	Tamper		Damage/	Nozzle/		HMIS
NUMBER# Location loc	<u> </u>	location	Visibility	Instr.Label	Seal	Weight	Corrosion	Hose	Gauge	Label
Reception Good	Ğ	DG DG	Good	Good	Good	Good	Good	Good	Good	Good
CONTROL	<u> </u>	g	Good	Good	Good	Good	Good	Good	Good	Good
VISITAYION Good	) (200	٦	Good	Good	Good	Good	Good	Good	Good	Good
LOBBY HALL WAY Good	9	٥	Good	Good	Good	Good	Good	Good	Good	Good
ADMIN HALL WAY Good	Coo	-	Good	Good	poog	Good	Good	Good	Good	Good
STAFF ENTRY Good	Gooc	1	Good	роод	Good	Good	Good	Good	Good	Good
STAFF LOUNGE Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
KITCHEN Good	G00			Good	Good	Good	Good	Good	Good	Good
LIBRARY	Good		Good	Good	Good	Good	Good	Good	Good	Good
	Good			Good	Good	Good	Good	Good	Good	Good
CLASSROOM B Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
WEIGHT ROOM Good	Good				Good	Good	Good	Good	Good	Good
VOCATIONAL Good	Good				Good	Good	Good	Good	Good	Good
INTAKE	Good		Good	Good	Good	Good	Good	Good	Good	Good
UNIT A DRYROOM Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
	Good		Good	Good	Good	Good	Good	Good	Good	Good
MV080685 UNIT A POD B Good	Good				Good	Good	Good	Good	Good	Good
_	Good		Good	Good	Good	Good	Good	Good	Good	Good
19 MV080720 UNIT B POD A Good	Good			Good	Good	Good	Good	Good	Good	Good
	Good	7			Good	Good	Good		Good	Good
GEN.RM.HALLWAY Good	Good	- 1			Good	Good	Good	Good	Good	Good
GENERATOR ROOM Good	Good		Good		Good	Good	Good	Good	Good	Good
MAINT.ROOM Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
BOILER ROOM Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
UNIT A AIRCON RM. Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
UNIT B AIRCON RM. Good	Good		Good	Good	Good	Good	Good	Good	Good	Good
	<u>.</u>									
		1								

ISTOMER			DATE	10/2 3/07		INSPECTOR	TOR:	JACK			
	MONTHLY INSPECTI	ON OF FI	<b>RE EXTIN</b>	FION OF FIRE EXTINGUISH, L.A.			SAFETY 18	st SYSTE	1st SYSTEM SAIPAN	ż	į
		Proper	Access/	Operating	Tamper			Nozzle/		HMIS	
NUMBER#	Location	location	Visibility	Instr.Label	Seal	Weight	Corrosion	Hose	Gauge	Label	
SN821588	Reception	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP784052	CONTROL	Good	Good	Good	Good	Good	Good	Good	9009	G00d	
SP784061	VISITAYION	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP787225	LOBBY HALL WAY	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP784059	ADMIN HALL WAY	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SN821590	STAFF ENTRY	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP784078	STAFF LOUNGE	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SN821604	KITCHEN	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP784079	LIBRARY	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP784062	CLASSROOM A	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SP784089	CLASSROOM B	Good	Good	Good	Good	Good	Good		Good	Good	
40	WEIGHT ROOM	900g	Good	Good	Good	Good	Good	Good	Good	Good	
13 MV080697	VOCATIONAL	Good	Good	Good	роод	Good	Good	Good	Good	Good	
14 MV080677	INTAKE	Good	Good		Good	Good	Good	Good	Good	Good	
15 MV080697	UNIT A DRYROOM	Good	Good	Good	Good	poog	Good	Good	Good	Good	
16 MV080684	UNIT A POD A	Good	Good	Good	Good	Good	Good	Good	Good	Good	
MV080685	UNIT A POD B	Good				Good	Good	Good	Good	Good	
18 RB661426	UNIT B DRYROOM	Good		Good	Good	Good	Good	poog	Good	Good	
19 MV080720	UNIT B POD'A			Good		Good	Good	Good	Good	Good	
20 MV080724	UNIT B POD A			Good	Good	Good	Good	poog	Good	Good	
SN821605	GEN.RM.HALLWAY	Good				Good	Good	Good	Good	Good	
SN821601	GENERATOR ROOM	Good	Good	Good		Good	Good	Good	Good	Good	
SP784065	MAINT.ROOM	Good	Good	Good	Good	Good	Good	Good	Good	Good	
SN821602		Good		Good		Good	Good	Good	Good	Good	
25 SN821600	UNIT A AIRCON RM.	Good	Good	Good (	Good	Good	Good	Good	Good	Good	
SN821603	UNIT B AIRCON RM.	Good	Good	Good	Good	Good	Good	Good (	Good	Good	
			:								
							_				

Case 1:99-cv-00017	iled 01/16/2008	Page 4 of 4
--------------------	-----------------	-------------

	:	т		-	ī											1	·				,	· 					1					····,		<del></del> -,	<del></del>	<del></del> ,	
Z.	HIMIS	Label	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
M SAIPA		Gauge	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
JACK st SYSTE	Nozzle/	Hose	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
FOR: JACK SAFETY 1st SYSTEM SAIPAN	Damage/	Corrosion	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
INSPECTOR: SAF		Weight	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	poog	Good	рооб	Good		Good	Good	poog	poog		Good	Good	Good									
	Tamper	Seal	Good	Good	Good	Good	рооб	Good	Good	Good	boog	poog	Good	рооб	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
9/; 007 3UIS: {	Operating	Instr.Label	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
DATE: RE EXTINÓ	Access/	Visibility		Good	Good	Good	Good	Good	Good	Good	Good	poog	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
ON OF FIF	Proper	location	Good	Good	Good	Good	poog	Good	poog	рооб	рооб	poog	Good	poog	Good	poog	Good	poog	Good	Good	Good	Good	Good	Good	Good	Good	Good	Good									
DYS-JDU  DATE: 9/ n07  MONTHLY INSPECTION OF FIRE EXTINGUIS. 1.	:			CONTROL	- 1	L WAY	WAY	STAFF ENTRY	STAFF LOUNGE	KITCHEN	LIBRARY	CLASSROOM A	CLASSROOM B	WEIGHT ROOM	VOCATIONAL	INTAKE	DRYROOM	UNIT A POD A	UNIT A POD B	UNIT B DRYROOM	UNIT B POD A	UNIT B POD A	-WAY	GENERATOR ROOM			UNIT A AIRCON RM.	UNIT B AIRCON RM.									
'USTOMER:	SERIAL	NUMBER#			3 SP784061	4 SP787225	5 SP784059	6 SN821590	7 SP784078	8 SN821604	9 SP784079	10 SP784062	11 SP784089	12 SP784064	13 MV080697	14 MV080677	15 MV080697	16 MV080684	17 MV080685	18 RB661426	19 MV080720	20 MV080724	21 SN821605		23 SP784065	24 SN821602	25 SN821600	26 SN821603	27	28	29	30	31	32	33	34	35